


## Description

This meter is used to measure crack that need not high precise measurement. This crack meter can be installed easy and check crack by naked eye.



## Specification

<b>Type</b>	<b>CM-100</b>
<b>Measurement Range</b>	±20mm(width), ±10mm(height)
<b>Resolution</b>	1 mm
<b>Dimension</b>	32 X 102 X 5 mm
<b>Installation</b>	Bolt or epoxy